

1924 Portland Tax Records: Dwelling, Caroline Street, Portland, 1924

L-150
3-5000

1-2
Maine
lot 34

Portland, Maine
Assessment 19


Name Estes Mellie G
Owner Caroline
Street Caroline No. 192
Block 193-D Lot 192
Use of Bldg. Dwelling Name _____
Tenants and Rooms Owner - 5
Rentals _____
Age 20
Condition of Repair Good

<input checked="" type="checkbox"/> Bungalow	<input checked="" type="checkbox"/> Exterior Clapboards	<input checked="" type="checkbox"/> Plumbing Common
<input checked="" type="checkbox"/> Single House	<input checked="" type="checkbox"/> Siding	<input checked="" type="checkbox"/> Individual
<input checked="" type="checkbox"/> Two family	<input checked="" type="checkbox"/> Shingles	<input checked="" type="checkbox"/> Open
<input checked="" type="checkbox"/> Three family	<input checked="" type="checkbox"/> Stucco	<input checked="" type="checkbox"/> Set tubs
<input checked="" type="checkbox"/> Apartment	<input checked="" type="checkbox"/> Paper	<input checked="" type="checkbox"/> Finish
<input checked="" type="checkbox"/> Store Building	<input checked="" type="checkbox"/> Tapestry Brick	<input checked="" type="checkbox"/> Plain
<input checked="" type="checkbox"/> Office	<input checked="" type="checkbox"/> Com. Brick	<input checked="" type="checkbox"/> Hardwood
<input checked="" type="checkbox"/> Factory	<input checked="" type="checkbox"/> Galv. Iron	<input checked="" type="checkbox"/> Halls
<input checked="" type="checkbox"/> Storage	<input checked="" type="checkbox"/> Stone	<input checked="" type="checkbox"/> Wood
<input checked="" type="checkbox"/> Stables	<input checked="" type="checkbox"/> Terra Cotta	<input checked="" type="checkbox"/> Terrazzo
<input checked="" type="checkbox"/> Garage, private	<input checked="" type="checkbox"/> Concrete	<input checked="" type="checkbox"/> Marble
<input checked="" type="checkbox"/> Garage, public		<input checked="" type="checkbox"/> Roof - Roofing
<input checked="" type="checkbox"/> Theatre	<input checked="" type="checkbox"/> Heating	<input checked="" type="checkbox"/> Shingle
<input checked="" type="checkbox"/> Club House	<input checked="" type="checkbox"/> Stove	<input checked="" type="checkbox"/> Slate
<input checked="" type="checkbox"/> Cottage	<input checked="" type="checkbox"/> Furnace	<input checked="" type="checkbox"/> Gravel
	<input checked="" type="checkbox"/> Hot Water	<input checked="" type="checkbox"/> Prepared
	<input checked="" type="checkbox"/> Steam	<input checked="" type="checkbox"/> Asbestos
<input checked="" type="checkbox"/> Foundation	<input checked="" type="checkbox"/> Light	<input checked="" type="checkbox"/> Flat
<input checked="" type="checkbox"/> Brick	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Hip
<input checked="" type="checkbox"/> Stone	<input checked="" type="checkbox"/> Gas	<input checked="" type="checkbox"/> Gable
<input checked="" type="checkbox"/> Concrete	<input checked="" type="checkbox"/> Electric	<input checked="" type="checkbox"/> Dormers - 2
<input checked="" type="checkbox"/> Pile		<input checked="" type="checkbox"/> Windows
<input checked="" type="checkbox"/> Basement	<input checked="" type="checkbox"/> Floor	<input checked="" type="checkbox"/> Plain Glass
<input checked="" type="checkbox"/> Full	<input checked="" type="checkbox"/> Common	<input checked="" type="checkbox"/> Wire Glass
<input checked="" type="checkbox"/> Cement Floor	<input checked="" type="checkbox"/> Hardwood	<input checked="" type="checkbox"/> Shutters
<input checked="" type="checkbox"/> Waterproof	<input checked="" type="checkbox"/> Re-Concrete	<input checked="" type="checkbox"/> Miscellaneous
<input checked="" type="checkbox"/> Construction	<input checked="" type="checkbox"/> Concrete Slab	<input checked="" type="checkbox"/> Elevator
<input checked="" type="checkbox"/> Frame	<input checked="" type="checkbox"/> Waterproof	<input checked="" type="checkbox"/> Sprinkler
<input checked="" type="checkbox"/> Brick	<input checked="" type="checkbox"/> Ceiling	<input checked="" type="checkbox"/> Fire Escape
<input checked="" type="checkbox"/> Tile	<input checked="" type="checkbox"/> Plaster	<input checked="" type="checkbox"/> Refrigerator
<input checked="" type="checkbox"/> Blocks	<input checked="" type="checkbox"/> Metal	<input checked="" type="checkbox"/> Vacuum Cleaner
<input checked="" type="checkbox"/> Stucco	<input checked="" type="checkbox"/> Panelled	<input checked="" type="checkbox"/> Safes and Vaults
<input checked="" type="checkbox"/> Re-Concrete	<input checked="" type="checkbox"/> Rough	<input checked="" type="checkbox"/> Telephone Equip.
<input checked="" type="checkbox"/> Mill		
<input checked="" type="checkbox"/> Steel Frame		

Ground Area 1459 sq. ft. Height 27'-16"
Cubic Feet 37149 Unit 18 cts.
Utility Dep. _____
Dep. 35 Per cent.
Sound Value, \$ 4346

Land 6846 Corner _____ Interior _____ Alley _____
Front _____ Depth _____ = _____ ft.
COMPUTATION


Area	Multiplier	Coefficient	
6846	114	7804	
Year	Unit	Coefficient	Land
19	15	7804	1390 45



193-D-19
Surveyed by Babson
MAY - 3 1924 (Remarks on other Side) 1-2

Remarks about Buildings

21 x 46 = 966 x 27 =
17 x 17 = 289 x 27 = 33885
12 x 17 = 204 x 16 = 3264
1459 37149



Remarks about Land

Remarks about Personal Property

CITY OF PORTLAND, MAINE
ASSESSORS DEPARTMENT

CHART	BLOCK
3	Building Volumes Checked <u>K.H.</u>
4	Building Values Placed
5	Building Values Extended <u>E.M.H.</u>
6	Land Only Questionnaire Made
7	Land Values Placed
8	Land Values Extended
9	Compared with 1923
10	Losses of Property Added

1924 Portland Tax Records: Dwelling, Caroline Street, Portland, 1924

www.mainememory.net/item/36041
Collections of City of Portland - Planning & Development



Owner: Nellie G Estes
Address: Caroline Street, Deering Highlands, Portland, Maine
Use: Dwelling - Single family
Local Code: Block 193D Lot 19 Book 11 Page 1
MMN item number: 36041