4

Portland,   **Maine**

Assessment 19

Name

Owner _Portland Terminal Co_ 984

Street _Congress_   No. _980_

Block _65 1-0¾_   Lot _7_

Use of Bldg. _____ Name _____

Tenants and Rooms _____

Rentals _____

Age _____ V.I.A

Condition of Repair _____

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	
Store Building	Tapestry Brick	**Finish**
Office "	Com. Brick	Plain
Factory "	Galv. Iron	Hardwood
Storage "	Stone	
Stables	Terra Cotta	**Halls**
Garage, private	Concrete	Wood
Garage, public		Terrazzo
Theatre	**Heating**	Marble
Club House	Stove	
Cottage	Furnace	**Roof—Roofing**
	Hot Water	Shingle
Foundation	Steam	Slate
Brick		Gravel
Stone		Prepared
Concrete	**Light**	Asbestos
Pile	Oil	Flat
	Gas	Hip
	Electric	Gable
		Dormers
Basement		
Full	**Floor**	**Windows**
Cement Floor	Common	Plain Glass
Waterpoof	Hardwood	Wire Glass
	Re-Concrete	Shutters
	Concrete Slab	
Construction	Waterproof	**Miscellaneous**
Frame		Elevator
Brick		Sprinkler
Tile		Fire Escape
Blocks	**Ceiling**	Refrigerator
Stucco	Plaster	Vacuum Cleaner
Re-Concrete	Metal	Safes and Vaults
Mill	Panelled	Telephone Equip.
Steel Frame	Rough	

Ground Area _____ Height _____

Cubic Feet _____ Unit _____ cts.

Utility Dep. _____

Dep. _____ Per cent.

Sound Value, $ _____

Land _6972_ Corner _____ Interior _____ Alley

Front _____ Depth _____ = _____ ft

COMPUTATION

Area	Multiplier	Coefficient
1972	65	4531

Year	Unit	Coefficient	Land Value
19	.45	4531	679
	15		900

Surveyed by _____

(over)

1924 Portland Tax Records: Assessor's Record, 980 Congress Street, Portland, 1924

Owner: Portland Terminal Co.
Address: 980 Congress Street, Libbytown, Portland, Maine
Use: Land only
Local Code: Block 65F Lot 7 Book 20 Page 1
MMN item number: 40053