

1924 Portland Tax Records: Assessor's Record, 120-124 Dartmouth Street, Portland, 1924

2-2

**Portland, Maine**

**Assessment 19**

Name *Hedden Jennie & Mildred C. Scott*  
 Owner *Hedden Jennie & Mildred C. Scott*  
 Street *Dartmouth* No. *50*  
 Block *116-A-* Lot *24*  
 Use of Bldg. *Garage* Name.....  
 Tenants and Rooms *2 cars - 12 room*  
 Rentals  *Goes with house*  
 Age *1924*  
 Condition of Repair *Good*

<b>Class</b>	<b>Exterior</b>	<b>Plumbing</b>
Bungalow	<input checked="" type="checkbox"/> Clapboards	Common
Single House	<input type="checkbox"/> Siding	Individual
Two family	<input type="checkbox"/> Shingles	Open
Three family	<input type="checkbox"/> Stucco	Set tubs
Apartment	<input type="checkbox"/> Paper	<b>Finish</b>
Store Building	<input type="checkbox"/> Tapestry Brick	Plan
Office "	<input type="checkbox"/> Com. Brick	Hardwood
Factory "	<input type="checkbox"/> Galv. Iron	<b>Halls</b>
Storage "	<input type="checkbox"/> Stone	Wood
Stables	<input type="checkbox"/> Terra Cotta	Terrazzo
<input checked="" type="checkbox"/> Garage, private	<input type="checkbox"/> Concrete	Marble
Garage, public	<b>Heating</b>	Roof - Roofing
Theatre	<input type="checkbox"/> Stove	Shingle
Club House	<input type="checkbox"/> Furnace	Slate
Cottage	<input type="checkbox"/> Hot Water	Gravel
	<input type="checkbox"/> Steam	<input checked="" type="checkbox"/> Prepared
<b>Foundation</b>	<b>Light</b>	Asbestos
Brick	<input type="checkbox"/> Oil	Flat
Stone	<input type="checkbox"/> Gas	<input checked="" type="checkbox"/> Hip
Concrete <i>Slab</i>	<input checked="" type="checkbox"/> Electric	Gable
Pile		Dormers
<b>Basement</b>	<b>Floor</b>	<b>Windows</b>
Full	Common	<input checked="" type="checkbox"/> Plain Glass
Cement Floor	Hardwood	Wire Glass
Waterproof	Re-Concrete	Shutters
<b>Construction</b>	<input checked="" type="checkbox"/> Concrete Slab	<b>Miscellaneous</b>
<input checked="" type="checkbox"/> Frame	Waterproof	Elevator
Brick	<b>Ceiling</b>	Sprinkler
Tile	Plaster	Fire Escape
Blocks	Metal	Refrigerator
Stucco	Panelled	Vacuum Cleaner
Re-Concrete	<input checked="" type="checkbox"/> Rough	Safes and Vaults
Mill		Telephone Equip.
Steel Frame		

Ground Area *396 #* Height *9'*  
 Cubic Feet *3564* Unit *10* *cts.*  
 Utility Dep. *0*  
 Dep. *0* Per cent.  
**Sound Value, \$ 356** *(350)*

Land..... Corner..... Interior..... Alley.....  
 Front..... Depth..... =.....ft.  
 COMPUTATION

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			

**Personal Property** Value

Animals..... No. .... \$.....  
 "..... ".....  
 "..... ".....  
 Dogs, Male..... Female.....  
 Auto..... Year.....  
 "..... ".....  
 Furniture..... Good.....  
 Musical Inst..... Good.....  
 Carriages..... Good..... No. ....  
 Other Personal Property.....  
 Surveyed by.....  
 (Remarks on other Side) *242*

*18 x 22 = 396 18 x 19 = 3564*

E 1.9' 22'

**Remarks about Land**

**Remarks about Personal Property**

1924 Portland Tax Records: Assessor's Record, 120-124 Dartmouth Street, Portland, 1924

**Owner:** Jennie J Hodsdon  
**Address:** 120-124 Dartmouth Street, Oakdale, Portland, Maine  
**Use:** Garage  
**Local Code:** Block 116A Lot 24 Book 27 Page 2  
**MMN item number:** 48124  
**Style:** Vernacular Victorian  
**Notes:** Mildred C. Scott is listed as co-owner.