

1924 Portland Tax Records: Assessor's Record, 99-103 Deerfield Road, Portland, 1924

2-2

Portland, Maine

**Assessment 19**

Name Faxon Nellie S. lot 59

Owner Faxon Nellie S.

Street Deerfield Rd No. 99-103

Block 111-A Lot 8

Use of Bldg. Garage Name.....

Tenants and Rooms 2 Car-flivvers counter 7

Rentals Gains with house

Age 1924

Condition of Repair Good

<b>Class</b>	<b>Exterior</b>	<b>Plumbing</b>
Bungalow	<input checked="" type="checkbox"/> Clapboards wide	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	
Store Building	Tapestry Brick	<b>Finish</b>
Office	Com. Brick	Plain
Factory	Galv. Iron	Hardwood
Storage	Stone	
<input checked="" type="checkbox"/> Stables	Terra Cotta	<b>Halls</b>
<input checked="" type="checkbox"/> Garage, private	Concrete	Wood
Garage, public		Terrazzo
Theatre		Marble
Club House	<b>Heating</b>	<b>Roof — Roofing</b>
Cottage	Stove	Shingle
	Furnace	Slate
	Hot Water	Gravel
	Steam	<input checked="" type="checkbox"/> Prepared
<b>Foundation</b>		Asbestos
Brick		Flat
Stone	<b>Light</b>	<input checked="" type="checkbox"/> Hip
<input checked="" type="checkbox"/> Concrete 5/6 6	Oil	Gable
Pile	Gas	Dormers
	Electric	
<b>Basement</b>		<b>Windows</b>
Full		<input checked="" type="checkbox"/> Plain Glass
Cement Floor	<b>Floor</b>	Wire Glass
Waterproof	Common	Shutters
	Hardwood	
<b>Construction</b>	Re-Concrete	<b>Miscellaneous</b>
<input checked="" type="checkbox"/> Frame	<input checked="" type="checkbox"/> Concrete Slab	Elevator
Brick	Waterproof	Sprinkler
Tile		Fire Escape
Blocks	<b>Ceiling</b>	Refrigerator
Stucco	Plaster	Vacuum Cleaner
Re-Concrete	Metal	Safes and Vaults
Mill	Panelled	Telephone Equip.
Steel Frame	<input checked="" type="checkbox"/> Rough	

Ground Area 540 Height 9'-7"

Cubic Feet 4660 Unit 10 cts.

Utility Dep. 0

Dep. 0 Per cent.

Sound Value, \$ 466

Land..... Corner..... Interior..... Alley

Front..... Depth..... =.....ft.

COMPUTATION

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			

**Personal Property** Value

Animals..... No..... \$.....

"....."

"....."

Dogs, Male..... Female.....

Auto..... Year.....

"....."

Furniture..... Good..... Common.....

Musical Inst..... Good..... Common.....

Carriages..... Good..... No..... Common.....

Other Personal Property.....

Surveyed by Johnson & Gully

(Remarks on other Side)

**Remarks about Buildings**

$10 \times 10 = 100$   $\times 7 = 700$

$20 \times 22 = 440$   $\times 9 = 3960$

540 4660

**Remarks about Land**

**Remarks about Personal Property**

Personal Property Value

Animals..... No..... \$.....

"....."

"....."

Dogs, Male..... Female.....

Auto..... Year.....

"....."

Furniture..... Good..... Common.....

Musical Inst..... Good..... Common.....

Carriages..... Good..... No..... Common.....

Other Personal Property.....

Surveyed by.....

(Remarks on other Side)

1924 Portland Tax Records: Assessor's Record, 99-103 Deerfield Road, Portland, 1924

**Owner:** Nellie S Eaton  
**Address:** 99-103 Deerfield Road, Oakdale, Portland, Maine  
**Use:** Garage  
**Local Code:** Block 111A Lot 8 Book 27 Page 2  
**MMN item number:** 48804  
**Style:** Utilitarian