

1924 Portland Tax Records: 93-97 Elizabeth Road, Portland, 1924

Portland, Maine
Assessment 19 Pt-86A
 Name *McIntosh Mary S.*
 Owner *McIntosh Mary S.*
 Street *Elizabeth Road* No. *93-97*
 Block *120 E* Lot *25 L*
 Use of Bldg. *Dwelling* Name.....
 Tenants and Rooms *Owner - 5 - unfinished*
 Rentals *Owner*
 Age *July 1924 (Barnik 1924)*
 Condition of Repair *Good - but not*
Not finished - 7.5 - 4-1-24
- 4-17-25

Class	Exterior	Plumbing
<input checked="" type="checkbox"/> Bungalow	Clapboards	Common
<input checked="" type="checkbox"/> Single House	Siding	Individual
<input checked="" type="checkbox"/> Two family	Shingles	Open
<input checked="" type="checkbox"/> Three family	Stucco	Set tubs
<input checked="" type="checkbox"/> Apartment	Paper	Finish
<input checked="" type="checkbox"/> Store Building	Tapestry Brick	Plain
<input checked="" type="checkbox"/> Office "	Com. Brick	Hardwood
<input checked="" type="checkbox"/> Factory "	Galv. Iron	Halls
<input checked="" type="checkbox"/> Storage "	Stone	Wood
<input checked="" type="checkbox"/> Stables	Terra Cotta	Terrazzo
<input checked="" type="checkbox"/> Garage, private	Concrete	Marble
<input checked="" type="checkbox"/> Garage, public		
<input checked="" type="checkbox"/> Theatre		
<input checked="" type="checkbox"/> Club House		
<input checked="" type="checkbox"/> Cottage		
Foundation	Heating	Roof - Roofing
<input checked="" type="checkbox"/> Brick	Stove	Shingle
<input checked="" type="checkbox"/> Stone	Furnace	Slate
<input checked="" type="checkbox"/> Concrete + blocks	Hot Water	Gravel
<input checked="" type="checkbox"/> Pile	Steam	Prepared
		Asbestos
		Flat
		Hip
		Gable
		Dormers - 2
Basement	Light	Windows
<input checked="" type="checkbox"/> Full	Oil	Plain Glass
<input checked="" type="checkbox"/> Cement Floor	Gas	Wire Glass
<input checked="" type="checkbox"/> Waterproof	Electric	Shutters
Construction	Floor	Miscellaneous
<input checked="" type="checkbox"/> Frame	Common	Elevator
<input checked="" type="checkbox"/> Brick	Hardwood	Sprinkler
<input checked="" type="checkbox"/> Tile	Re-Concrete	Fire Escape
<input checked="" type="checkbox"/> Blocks	Concrete Slab	Refrigerator
<input checked="" type="checkbox"/> Stucco	Waterproof	Vacuum Cleaner
<input checked="" type="checkbox"/> Re-Concrete		Safes and Vaults
<input checked="" type="checkbox"/> Mill		Telephone Equip.
<input checked="" type="checkbox"/> Steel Frame		

Ground Area *1008 sq ft* Height *20'*
 Cubic Feet *20160* Unit *18* dis.
 Utility Dep. *25*
 Dep. *5* Per cent.
 Sound Value, \$ *2456*
 Land *3247* Corner..... Interior..... Alley
 Front..... Depth..... =..... ft.
 COMPUTATION *1926 - 2600*
R1934

Area	Multiplier	Coefficient	
<i>3247</i>	<i>130</i>	<i>4221</i> X	
Year	Unit	Coefficient	Land Value
<i>19</i>	<i>.06</i>	<i>4221</i>	<i>\$253</i> (250)



Remarks about Buildings

28 x 36 = 1008' x 20' = 20160

Remarks about Land

Remarks about Personal Property

CITY OF PORTLAND, MAINE		
ASSESSORS DEPARTMENT		
CHART	BLOCK	
3	Building Volumes Checked	<i>Y</i>
4	Building Values Placed	<i>Y</i>
5	Building Values Extended	<i>Y</i>
6	Land Copy Questionnaire Made	
7	Land Values Placed	
8	Land Values Extended	
9	Compared with 1923	
10	Personal Property Added	

1924 Portland Tax Records: 93-97 Elizabeth Road, Portland, 1924

www.maine-memory.net/ftem/49981
Collections of City of Portland - Planning & Development



Owner: Mary S McIntosh
Address: 93-97 Elizabeth Road, Libbytown, Portland, Maine
Use: Bungalow
Local Code: Block 120E Lot 25 Book 29 Page 1
MMN item number: 49981