

1924 Portland Tax Records: 66-68 Grant Street, Portland, 1924

Portland, Maine  
 Assessment 19  
 Name Davis Carrie C  
 Owner Davis Carrie C  
 Street Grant No. 66-68  
 Block 48 D Lot 7  
 Use of Bldg. DWELLING Name \_\_\_\_\_  
 Tenants and Rooms 1 Name \_\_\_\_\_  
 Rentals Owner occupies 2 Rms. rented \$200.00  
 Age 39 YEARS  
 Condition of Repair GOOD

<b>Class</b>	<b>Exterior</b>	<b>Plumbing</b>
<input checked="" type="checkbox"/> Bungalow	<input checked="" type="checkbox"/> Clapboards	<input checked="" type="checkbox"/> Common
<input checked="" type="checkbox"/> Single House	<input checked="" type="checkbox"/> Siding	<input checked="" type="checkbox"/> Individual
<input checked="" type="checkbox"/> Two family	<input checked="" type="checkbox"/> Shingles	<input checked="" type="checkbox"/> Open
<input checked="" type="checkbox"/> Three family	<input checked="" type="checkbox"/> Stucco	<input checked="" type="checkbox"/> Set tubs
<input checked="" type="checkbox"/> Apartment	<input checked="" type="checkbox"/> Paper	<b>Finish</b>
<input checked="" type="checkbox"/> Store Building	<input checked="" type="checkbox"/> Tapestry Brick	<input checked="" type="checkbox"/> Plain
<input checked="" type="checkbox"/> Office	<input checked="" type="checkbox"/> Com. Brick	<input checked="" type="checkbox"/> Hardwood
<input checked="" type="checkbox"/> Factory	<input checked="" type="checkbox"/> Galv. Iron	<b>Halls</b>
<input checked="" type="checkbox"/> Storage	<input checked="" type="checkbox"/> Stone	<input checked="" type="checkbox"/> Wood
<input checked="" type="checkbox"/> Stables	<input checked="" type="checkbox"/> Terra Cotta	<input checked="" type="checkbox"/> Terrazzo
<input checked="" type="checkbox"/> Garage, private	<input checked="" type="checkbox"/> Concrete	<input checked="" type="checkbox"/> Marble
<input checked="" type="checkbox"/> Garage, public	<b>Heating</b>	<b>Roof - Roofing</b>
<input checked="" type="checkbox"/> Theatre	<input checked="" type="checkbox"/> Stove	<input checked="" type="checkbox"/> Shingle
<input checked="" type="checkbox"/> Club House	<input checked="" type="checkbox"/> Furnace	<input checked="" type="checkbox"/> Slate
<input checked="" type="checkbox"/> Cottage	<input checked="" type="checkbox"/> Hot Water	<input checked="" type="checkbox"/> Gravel
<b>Foundation</b>	<input checked="" type="checkbox"/> Steam	<input checked="" type="checkbox"/> Prepared
<input checked="" type="checkbox"/> Brick	<b>Light</b>	<input checked="" type="checkbox"/> Asbestos
<input checked="" type="checkbox"/> Stone	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Flat
<input checked="" type="checkbox"/> Concrete	<input checked="" type="checkbox"/> Gas <u>STOVE</u>	<input checked="" type="checkbox"/> Hip
<input checked="" type="checkbox"/> Pile	<input checked="" type="checkbox"/> Electric	<input checked="" type="checkbox"/> Gable
<b>Basement</b>	<b>Floor</b>	<input checked="" type="checkbox"/> Dormers
<input checked="" type="checkbox"/> Full	<input checked="" type="checkbox"/> Common <u>8</u>	<b>Windows</b>
<input checked="" type="checkbox"/> Cement Floor	<input checked="" type="checkbox"/> Hardwood <u>5</u>	<input checked="" type="checkbox"/> Plain Glass
<input checked="" type="checkbox"/> Waterproof	<input checked="" type="checkbox"/> Re-Concrete	<input checked="" type="checkbox"/> Wire Glass
<b>Construction</b>	<input checked="" type="checkbox"/> Concrete Slab	<input checked="" type="checkbox"/> Shutters
<input checked="" type="checkbox"/> Frame	<input checked="" type="checkbox"/> Waterproof	<b>Miscellaneous</b>
<input checked="" type="checkbox"/> Brick	<b>Ceiling</b>	<input checked="" type="checkbox"/> Elevator
<input checked="" type="checkbox"/> Tile	<input checked="" type="checkbox"/> Plaster	<input checked="" type="checkbox"/> Sprinkler
<input checked="" type="checkbox"/> Blocks	<input checked="" type="checkbox"/> Metal	<input checked="" type="checkbox"/> Fire Escape
<input checked="" type="checkbox"/> Stucco	<input checked="" type="checkbox"/> Panelled	<input checked="" type="checkbox"/> Refrigerator
<input checked="" type="checkbox"/> Re-Concrete	<input checked="" type="checkbox"/> Rough	<input checked="" type="checkbox"/> Vacuum Cleaner
<input checked="" type="checkbox"/> Mill		<input checked="" type="checkbox"/> Safes and Vaults
<input checked="" type="checkbox"/> Steel Frame		<input checked="" type="checkbox"/> Telephone Equip.

Ground Area 1414 Height 22' 2 1/2"  
 Cubic Feet 27000 Unit 16 cts.  
 Utility Dep. \_\_\_\_\_  
 Dep. 40 Per cent.  
 - Sound Value, \$ 3937

Land 4750 Corner \_\_\_\_\_ Interior \_\_\_\_\_ Alley \_\_\_\_\_  
 Front \_\_\_\_\_ Depth \_\_\_\_\_ = \_\_\_\_\_ ft.  
 COMPUTATION

Area	Multiplier	Coefficient
4750	102	4845
Year	Unit	Coefficient
19	50	4845
		2180
		2422

Surveyed by C. F. Higgins  
 (Remarks on other Side) 1 of 2



**Remarks about Buildings**  
 2 Story frame house  
 $10.75 \times 9'0" = 96.75$   
 $18'0" \times 30'6" = 549$   
 $25'0" \times 32'0" = 800$   
 $9'0" \times 585 = 5265$   
 $27'0" \times 14823 = 399221$   
 $32'0" \times 25600 = 817600$   
 1414 ✓ 41808 ✓

**Remarks about Land**

Grant St.

**Remarks about Personal Property**

CITY OF PORTLAND, MAINE  
 ASSESSORS DEPARTMENT

CHART	BLOCK
3	Building Volumes Checked
4	Building Values Placed
5	Building Values Extended
6	Land Only Questionnaire Made
7	Land Values Placed
8	Land Values Extended
9	Compared With 1923
10	Personal Property Added

Handwritten notes: f.u. 2180, 2422, 2175

1924 Portland Tax Records: 66-68 Grant Street, Portland, 1924



**Owner:** Carrie C. Davis  
**Address:** 66-68 Grant Street, Parkside, Portland, Maine  
**Use:** Dwelling - Single family  
**Local Code:** Block 48D Lot 7 Book 40 Page 1  
**MMN item number:** 56828