
1924 Portland Tax Records: 67 Merrill Street, Portland, 1924

Po ind, Maine Assessment 19 Name Owner Dunn John ... No. 67 Street Merrill Lot 20 Block 15 D Tenants and Rooms One Tenar Age Condition of Repair Fair Class Bungalow Single House Two family Apartment Store Building Ofice " Factory " Storage " Starage, private Garage, public Theatre Club House Cottage Exterior —Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Ieating Plumbing -NoBath Common Individual Open Set tubs Finish Plain Hardwood Halls Wood Terrazzo Marble Marble Roof — Roofing -Shingle Slate Gravel Prepared Asbestos Flat Hip -Gable Dormers Windows Heating Stove Furnace Hot Water Steam Foundation Brick Stone Concrete - Pile Light Gas – Electric Basement Full --Cement Floor Waterproof Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Windows —Plain Glass Wire Glass Shutters Construction Miscellaneous Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip. Ceiling Plaster Metal Panelled Rough Height 23'-19 Ground Area 1923.3.1 Cubic Feetcts. Utility Dep.Per cent. Dep. Sound Value, \$ 268 Land 2391 Corner Interior Alley Front Depth=..... ..ft. COMPUTATION Multiplier Coefficient Area 2582 2 9 Land Value Unit Coefficient Year 19 \$10 Y- 2800 Surveyed by (Remarks on other Side)



1924 Portland Tax Records: 67 Merrill Street, Portland, 1924



Owner:	John Dunn
Address:	67 Merrill Street, East End - Munjoy Hill, Portland, Maine
Use:	Dwelling - Single family
Local Code:	Block 15D Lot 20 Book 50 Page 1
MMN item number:	62985