

Portland, Maine
Assessment 19
 Name Cushing's Island Realty Co
 Owner Cushing's Island No. _____
 Street _____
 Block _____ Lot _____
 Use of Bldg. Shed Name _____
 Tenants and Rooms Owner
 Rentals Owner
 Age 40-50
 Condition of Repair Fair
 44119-1D

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	
Store Building	Tapestry Brick	Finish
Office	Com. Brick	Plain
Factory	Galv. Iron	Hardwood
Storage	Stone	Halls
Stables	Terra Cotta	Wood
Garage, private	Concrete	Terrazzo
Garage, public		Marble
Theatre		Floor-Roofing
Club House	Heating	Shingle
Cottage	Stove	Slate
Foundation	Furnace	Gravel
Brick	Hot Water	Prepared
Stone	Steam	Asbestos
Concrete		Flat
Pile	Light	Hip
Basement	Oil	Gable
Full	Gas	Dormers
Cement Floor	Electric	
Waterproof		Windows
	Floor	Plain Glass
Construction	Common	Wire Glass
Frame	Hardwood	Shutters
Brick	Re-Concrete	
Tile	Concrete Slab	Miscellaneous
Blocks	Waterproof	Elevator
Stucco		Sprinkler
Re-Concrete	Ceiling	Fire Escape
Mill	Plaster	Refrigerator
Steel Frame	Metal	Vacuum Cleaner
	Panelled	Safes and Vaults
	Rough	Telephone Equip.

Ground Area _____ Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____

Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.

COMPUTATION

50 Shed
 50 henhouse } 75

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			

Surveyed by W. V. Johnson
 44119-1D
 5-10

Portland, Maine
Assessment 19
 Name _____
 Owner _____
 Street _____ No. _____
 Block _____ Lot _____
 Use of Bldg. _____ Name _____
 Tenants and Rooms _____
 Rentals _____
 Age _____
 Condition of Repair _____

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	
Store Building	Tapestry Brick	Finish
Office	Com. Brick	Plain
Factory	Galv. Iron	Hardwood
Storage	Stone	Halls
Stables	Terra Cotta	Wood
Garage, private	Concrete	Terrazzo
Garage, public		Marble
Theatre		Floor-Roofing
Club House	Heating	Shingle
Cottage	Stove	Slate
Foundation	Furnace	Gravel
Brick	Hot Water	Prepared
Stone	Steam	Asbestos
Concrete		Flat
Pile	Light	Hip
Basement	Oil	Gable
Full	Gas	Dormers
Cement Floor	Electric	
Waterproof		Windows
	Floor	Plain Glass
Construction	Common	Wire Glass
Frame	Hardwood	Shutters
Brick	Re-Concrete	
Tile	Concrete Slab	Miscellaneous
Blocks	Waterproof	Elevator
Stucco		Sprinkler
Re-Concrete	Ceiling	Fire Escape
Mill	Plaster	Refrigerator
Steel Frame	Metal	Vacuum Cleaner
	Panelled	Safes and Vaults
	Rough	Telephone Equip.

Ground Area _____ Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____

Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.

COMPUTATION

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value

www.maine-memory.net/item/68575
Collections of City of Portland - Planning & Development



Owner: Cushing's Island Hotel & Realty Company
Address: Cushing's Island, Cushing's Island, Portland, Maine
Use: Shed
Local Code: Block 106A Lot C4 Book 89 Page 5
MMN item number: 68575