


1924 Portland Tax Records: Wilson property, Oakland Avenue, Peaks Island, Portland, 1924

Portland, Maine
 Assessment 19
 Name
 Owner Wilson, Sarah
 Street Oakland Ave. No. _____
 Block 84-B 84-B-9 Lot 12
 Use of Bldg. S.D. Name _____
 Tenants and Rooms 1-3
 Rentals _____
 Age 4
 Condition of Repair Fair
 _____ 189-A

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapes try Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete	Plumbing Common Individual Open Set tubs <u>W.H.V.</u> Finish Plain Hardwood Halls Wood Terrazzo <u>Rough</u> Marble
Foundation Brick Stone Concrete Pile	Heating Stove Furnace Hot Water Steam <u>Gas store</u> Light Oil Gas Electric	Foof-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers
Basement Full Cement Floor Waterproof	Floor Common Hardwood Re-Concrete Concrete Slab Waterproof	Windows Plain Glass Wire Glass Shutters
Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Ceiling Plaster Metal Panelled Rough	Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.

Ground Area 396-15 Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____
 Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.
 COMPUTATION
450-1931-400

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			



Surveyed by _____
 (over) △ 2-2

Portland, Maine
 Assessment 19
 Name _____
 Owner _____
 Street _____ No. _____
 Block _____ Lot _____
 Use of Bldg. _____ Name _____
 Tenants and Rooms _____
 Rentals _____
 Age _____
 Condition of Repair _____
 _____ 18x22 = 396-15

_____ 189-A

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapes try Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete	Plumbing Common Individual Open Set tubs <u>W.H.V.</u> Finish Plain Hardwood Halls Wood Terrazzo <u>Rough</u> Marble
Foundation Brick Stone Concrete Pile	Heating Stove Furnace Hot Water Steam <u>Gas store</u> Light Oil Gas Electric	Foof-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers
Basement Full Cement Floor Waterproof	Floor Common Hardwood Re-Concrete Concrete Slab Waterproof	Windows Plain Glass Wire Glass Shutters
Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Ceiling Plaster Metal Panelled Rough	Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.

Ground Area 396-15 Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____
 Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.
 COMPUTATION

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			

Surveyed by _____
 (over)

1924 Portland Tax Records: Wilson property, Oakland Avenue, Peaks Island, Portland, 1924



Owner: Sarah Wilson
Address: Oakland Avenue, Peaks Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 84B Lot 9 Book 98 Page 2
MMN item number: 82495
Style: Cottage