

Portland, Maine
Assessment 19
 Name *Taylor 2001 m*
 Owner *Charles Harry G*
 Street *E. Side Torrington Ave* No. *75 35-36*
 Block *84-A* *84 N-16* Lot *78*
 Use of Bldg. *RD* Name
 Tenants and Rooms *1-7*
 Rentals
 Age *15+*
 Condition of Repair *Fair* 733A

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete	Plumbing Common Individual Open Set tubs <i>H.W.</i>
Foundation Brick Stone Concrete Pile	Heating Stove Furnace Hot Water Steam Oil Gas Electric	Finish Plain Hardwood
Basement Full Cement Floor Waterproof	Floor Common Hardwood Re-Concrete Concrete Slab Waterproof	Halls Wood Terrazzo Marble
Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Ceiling Plaster Metal Panelled Rough	Foot-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers
		Windows Plain Glass Wire Glass Shutters
		Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.


Ground Area *620-25* Height
 Cubic Feet Unit cts.
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land *3036* Corner Interior Alley
 Front Depth = ft.

COMPUTATION

150
~~*1100*~~ *\$1150.*
1930 - *1931* *\$1025*

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			



733A

Surveyed by.....

(over)

1924 Portland Tax Records: Tayloy property, E. Side Torrington Avenue, Peaks Island, Portland, 1924



Owner: Lois M. Tayloy
Address: E. Side Torrington Avenue, Peaks Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 84N Lot 16 Book 98 Page 1
MMN item number: 82842