

Portland, Maine
 Assessment 19 **L 200 B 400**
 Name **Oliver Gertrude M**
 Street **Peaks Island**
 Block **90** Lot **10-2-7**
 Use of Bldg. **S.D.** Name **2Kelle**
 Tenants and Rooms **1-5**
 Rentals **owner**
 Age **40+**
 Condition of Repair **Fair** **160**


Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	
Store Building	Tapestry Brick	Finish
Office	Com. Brick	Plain
Factory	Galv. Iron	Hardwood
Storage	Stone	
Stables	Terra Cotta	Halls
Garage, private	Concrete	Wood
Garage, public		Terrazzo
Theatre		Marble
Club House	Heating	Roof - Roofing
Cottage	Stove	Shingle
	Furnace	Slate
	Hot Water	Gravel
	Steam	Prepared
Foundation		Asbestos
Brick	Light	Flat
Stone	Oil	Hip
Concrete	Gas	Gable
Pile	Electric	Dormers
Basement		Windows
Full		Plain Glass
Cement Floor	Floor	Wire Glass
Waterproof	Common	Shutters
	Hardwood	
Construction	Re-Concrete	Miscellaneous
Frame	Concrete Slab	Elevator
Brick	Waterproof	Sprinkler
Tile		Fire Escape
Blocks	Ceiling	Refrigerator
Stucco	Plaster	Vacuum Cleaner
Re-Concrete	Metal	Safts and Vaults
Mill	Panelled	Telephone Equip.
Steel Frame	Rough	

Ground Area **476-1/2 S** Height.....
 Cubic Feet..... Unit.....cts.
 Utility Dep.....
 Dep.....Per cent.
Sound Value, \$.....

Land **4100** Corner..... Interior..... Alley.....
 Front..... Depth.....ft.
 COMPUTATION
1.50
650-1931-4575

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			



Surveyed by.....
 (Remarks on other Side) **8**

Remarks about Buildings

(1 1/2)

10 x 14 = 140
 14 x 24 = 336
 476 - 125

Remarks about Land

Remarks about Personal Property

Surveyed by.....
 (Remarks on other Side)



Owner: Gertrude M. Oliver
Address: Rear West Side Island Avenue, Peaks Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 90D Lot 7 Book 99 Page 1
MMN item number: 83698