

Port 1, Assessment 19 **L 300** **B 400** **1-2**

Name **Merrill Martha A**
 Street **Long Island S W side Beach Ave**
 Block **93** **93-2-7** Lot
 Use of Bldg. **SD** Name
 Tenants and Rooms **Leant-6**
 Rentals **Vacant**
 Age **25**
 Condition of Repair **Fair** **2188**

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	Finish
Store Building	Tapestry Brick	Plain
Office "	Com. Brick	Hardwood
Factory "	Galv. Iron	Halls
Storage	Stone	Wood
Stables	Terra Cotta	Terrazzo
Garage, private	Concrete	Marble
Garage, public		
Theatre		
Club House	Heating	Roof - Roofing
Cottage	Stove	Shingle
	Furnace	Slate
	Hot Water	Gravel
	Steam	Prepared
Foundation		Asbestos
Brick	Light	Flat
Stone	Oil	Hip
Concrete	Gas	Gable
Pile	Electric	Dormers
Basement No		
Full	Floor	Windows
Cement Floor	Common	Plain Glass
Waterproof	Hardwood	Wire Glass
	Re-Concrete	Shutters
Construction	Concrete Slab	Miscellaneous
Frame	Waterproof	Elevator
Brick		Sprinkler
Tile	Ceiling	Fire Escape
Blocks	Plaster	Refrigerator
Stucco	Metal	Vacuum Cleaner
Re-Concrete	Panelled	Safes and Vaults
Mill	Rough	Telephone Equip.
Steel Frame		

Ground Area **640-1/2-S** Height
 Cubic Feet Unit
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land **33000** Corner Interior Alley
 Front Depth = ft.

COMPUTATION
250
500-1931 \$450

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			



Surveyed by **W. W. Johnson**
 (Remarks on other Side)

Remarks about Buildings

Remarks about Land

Remarks about Personal Property

www.mainmemory.net/item/83903
Collections of City of Portland - Planning & Development



Owner: Martha A Merrill
Address: Southwest side Beach Avenue, Long Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 93I Lot 7 Book 91 Page 1
MMN item number: 83903