

1924 Portland Tax Records: Shelvey property, N. Side Winding Way, Peaks Island, Portland, 1924

Sullivan, Marguerite, 1923
 Portland, Maine
 Assessment 19
 Name *Shelvey Sarah A.*
 Owner *Shelvey Sarah A.*
 Street *Winding Way* No. *lot 120*
 Block *85-A* *85-T-33* Lot *31*
 Use of Bldg. *1-7* Name *Shelvey*
 Tenants and Rooms *1-7*
 Rentals *None*
 Age *20*
 Condition of Repair *Plaint*
777A 1109

Class Bangalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage Foundation Brick Stone Concrete Pile Basement Full Cement Floor Waterproof Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame Ground Area <i>780-78</i> Cubic Feet Utility Dep. Dep. Per cent. Sound Value, \$ Land <i>4144</i> Corner Interior Alley Front Depth = ft. COMPUTATION <i>100</i> <i>1100 - 1751 - 1000</i>	Exterior Clapboards Siding Shingles Stucco Paper Tapes try Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Heating Stove Furnace Hot Water Steam Light Oil Gas Electric Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Ceiling Plaster Metal Panelled Rough <i>2 B Braid.</i>	Plumbing Common Individual Open Set tubs Finish Plain Com. Brick Hardwood Halls Wood Terrazzo Marble Roof-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Plain Glass Wire Glass Shutters Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
---	---	--



Surveyed by _____

(over)

Portland, Maine
 Assessment 19
 Name _____
 Owner _____
 Street _____ No. _____
 Block _____ Lot _____
 Use of Bldg. _____ Name _____
 Tenants and Rooms _____
 Rentals _____
 Age _____
 Condition of Repair _____
26'
10'
26' x 30' = 780 - 15

Class Bangalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage Foundation Brick Stone Concrete Pile Basement Full Cement Floor Waterproof Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame Ground Area <i>780-78</i> Cubic Feet Utility Dep. Dep. Per cent. Sound Value, \$ Land <i>4144</i> Corner Interior Alley Front Depth = ft. COMPUTATION <i>100</i> <i>1100 - 1751 - 1000</i>	Exterior Clapboards Siding Shingles Stucco Paper Tapes try Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Heating Stove Furnace Hot Water Steam Light Oil Gas Electric Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Ceiling Plaster Metal Panelled Rough <i>2 B Braid.</i>	Plumbing Common Individual Open Set tubs Finish Plain Com. Brick Hardwood Halls Wood Terrazzo Marble Roof-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Plain Glass Wire Glass Shutters Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
---	---	--



Surveyed by _____

(over)

1924 Portland Tax Records: Shelvey property, N. Side Winding Way, Peaks Island, Portland, 1924



Owner: Sarah A. Shelvey
Address: N. Side Winding Way, Peaks Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 85J Lot 33 Book 99 Page 1
MMN item number: 84375
Notes: "Lone Pine".