


1924 Portland Tax Records: Robinson property, S. Side Maple Street, Peaks Island, Portland, 1924

Portland, Maine
Assessment 19
 Name *Robinson*
 Owner *Robinson Walter B*
 Street *S. Side Maple St* No. _____
 Block *85-A 85-0-7-30-3* Lot *65-66*
 Use of Bldg. *Garage* Name _____
 Tenants and Rooms *1-1 car*
 Rentals *none*
 Age *14*
 Condition of Repair *Fair*
(built from old lumber) 223-A

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stones Terra Cotta Concrete	Plumbing Common Individual Open Set tubs	Finish Plain Hardwood	Halls Wood Terrazzo Marble	Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers	Windows Plain Glass Wire Glass Shutters	Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
Foundation Brick Stone Concrete Pile	Light Oil Gas Electric	Basement Full Cement Floor Waterproof	Floor Common Hardwood Re-Concrete Concrete Slab Waterproof	Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Ceiling Plaster Metal Panelled Rough	Ground Area <i>180-15</i> Height _____	Cubic Feet _____ Unit _____ cts. _____
Utility Dep. _____		Dep. _____ Per cent. _____		Sound Value, \$ _____			
Land _____ Corner _____ Interior _____ Alley _____	Front _____ Depth _____ = _____ ft.		COMPUTATION				

100

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value



223A

Surveyed by _____

2-3

(over)

Portland, Maine
Assessment 19
 Name _____
 Owner _____
 Street _____ No. _____
 Block _____ Lot _____
 Use of Bldg. _____ Name _____
 Tenants and Rooms _____
 Rentals _____
 Age _____
 Condition of Repair _____

10x18 = 180-15

(1)

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stones Terra Cotta Concrete	Plumbing Common Individual Open Set tubs	Finish Plain Hardwood	Halls Wood Terrazzo Marble	Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers	Windows Plain Glass Wire Glass Shutters	Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
Foundation Brick Stone Concrete Pile	Light Oil Gas Electric	Basement Full Cement Floor Waterproof	Floor Common Hardwood Re-Concrete Concrete Slab Waterproof	Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Ceiling Plaster Metal Panelled Rough	Ground Area _____ Height _____	Cubic Feet _____ Unit _____ cts. _____
Utility Dep. _____		Dep. _____ Per cent. _____		Sound Value, \$ _____			
Land _____ Corner _____ Interior _____ Alley _____	Front _____ Depth _____ = _____ ft.		COMPUTATION				

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value

(over)

1924 Portland Tax Records: Robinson property, S. Side Maple Street, Peaks Island, Portland, 1924



Owner: Walter B. Robinson
Address: S. Side Maple Street, Peaks Island, Portland, Maine
Use: Garage
Local Code: Block 850 Lot 7 Book 97 Page 1
MMN item number: 85053