

Portland, Maine
 Assessment 19
 Name *Cushman Nathan A.* 2-4
 Owner *Cushman Nathan A.*
 Street *Centennial St.* No.
 Block *87-V-1* Lot
 Use of Bldg. *Bar* Name
 Tenants and Rooms *1-2*
 Rentals *Owner*
 Age
 Condition of Repair *Poor*
694B


| | | |
|---|---|--|
| Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage | Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete <i>Logs</i> Heating Stove Furnace Hot Water Steam | Plumbing Common Individual Open Set tubs Finish Plain Hardwood Halls Wood Terrazzo Marble Floor-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers |
| Foundation Brick Stone Concrete Pile | Light Oil Gas Electric | Windows Plain Glass Wire Glass Shutters |
| Basement Full Cement Floor Waterproof <i>None</i> Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame | Floor Common Hardwood Concrete Concrete Slab Waterproof | Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip. |

Ground Area *405-35* Height
 Cubic Feet Unit cts.
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land Corner Interior Alley
 Front Depth = ft.
 COMPUTATION

200-1931-4175

| Area | Multiplier | Coefficient | |
|------|------------|-------------|------------|
| | | | |
| Year | Unit | Coefficient | Land Value |
| 19 | | | |



Surveyed by
 (over) 2-4

Portland, Maine
 Assessment 19
 Name
 Owner
 Street No.
 Block Lot
 Use of Bldg. Name
 Tenants and Rooms
 Rentals
 Age
 Condition of Repair

Built of old material

X

15 x 27 = 405-25

| | | |
|--|---|--|
| Plumbing Common Individual Open Set tubs Finish Plain Hardwood Halls Wood Terrazzo Marble Floor-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers | Windows Plain Glass Wire Glass Shutters | Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip. |
|--|---|--|

Ground Area Height
 Cubic Feet Unit cts.
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land Corner Interior Alley
 Front Depth = ft.
 COMPUTATION

| Area | Multiplier | Coefficient | |
|------|------------|-------------|------------|
| | | | |
| Year | Unit | Coefficient | Land Value |
| 19 | | | |

Surveyed by
 (over)



Owner: Nathan A. Cushman
Address: E. Side Centennial Street, Peaks Island, Portland, Maine
Use: Barn
Local Code: Block 87V Lot 1 Book 97 Page 2
MMN item number: 85130