1924 Portland Tax Records: Waite property, E. side Island Avenue, rear, Peaks Island, Portland, 1924

Port. d. aine Assessment 19 Name Waite Lizzie E Street Peaks Island War Greilp thank un Owner Block 92 X Lot Use of Bldg. 8. 10. Name. Tenants and Rooms. 1. - le. Rentals Age .. 40 Condition of Repair Good. Exterior —Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Class Bungalow —Single House Two family Three family Apartment Store Building Office " Factory " Storage Plumbing Common Individual Open Set tubs Finish Plain Hardwood (Halls) Walls Wood Rough Terrazzo Marble Storage Stables Stables Garage, private Garage, public Theatre Club House Cottage Marble Roof -- Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Heating Stove Furnace Hot Water Steam Foundation Brick Stone Concrete Pile Light Oil Gas Electric Basement Windows -Plain Glass Wire Glass Shutters Full Cement Floor Waterproof Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Construction Miscellaneous Elevator Sprinkler Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip. Ceiling Plaster Metal Panelled 2 B. Board Ground Area ... Height ... 125 225 Cubic Feet Unit. cts Utility Dep.Per cent. Dep. Sound Value, \$ Land 6046 Corner Interior ... Alley Front Depth=.... ...ft. COMPUTATION 125-7:00-19 625 Area Multiplier Coefficient Land Value Unit Coefficient Year 19

Remarks about Buildings (1)6 2(12) 16' 120 6×20= 10×14 260 -15 14×11=224-125 64 **Remarks** about Land **Remarks about Personal Property**

1924 Portland Tax Records: Waite property, E. side Island Avenue, rear, Peaks Island, Portland, 1924



Owner:	Lizzie E. Waite
Address:	E. side Island Avenue, rear, Peaks Island, Portland, Maine
Use:	Summer Dwelling
Local Code:	Block 92E Lot 28-29 Book 96 Page 1
MMN item number:	: 85914