

*L-100*  
*B-300*


Portland, Maine  
 Assessment 19 *L100*  
 Name *Smith Lillian A*  
 Owner *Smith Lillian A*  
 Street *Rear Seashore Ave, No.*  
 Block *85-A* *85-F-18* Lot *254*  
 Use of Bldg. *S.O.* Name *Lockman*  
 Tenants and Rooms *1-6*  
 Rentals *\$100 per season*  
 Age *215*  
 Condition of Repair *Fair*  
*1106*

<b>Class</b> Bungalow Single House Two family Three family Apartment Store Building Office Factory Stables Garage, private Garage, public Theatre Club House Cottage	<b>Exterior</b> Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete	<b>Plumbing</b> Common Individual Open Set tubs	<b>Finish</b> Plain Hardwood	<b>Halls</b> Wood Terrazzo Marble	<b>Foot-Roofing</b> Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers	<b>Windows</b> Plain Glass Wire Glass Shutters	<b>Miscellaneous</b> Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
<b>Foundation</b> Brick Stone Concrete Pile	<b>Heating</b> Stove Furnace Hot Water Steam	<b>Light</b> Oil Gas Electric	<b>Floor</b> Common Hardwood Re-Concrete Concrete Slab Waterproof	<b>Ceiling</b> Plaster Metal Panelled Rough	<b>Basement</b> Full Cement Floor Waterproof	<b>Construction</b> Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	

*Accented Ave*  
 Ground Area *500-1/2* Height  
 Cubic Feet Unit cts.  
 Utility Dep.  
 Dep. Per cent.  
**Sound Value, \$**  
 Land *7500* Corner Interior Alley  
 Front Depth = ft.  
 COMPUTATION  
*75*  
*600 - Paid 700 for this furnished in 1919*  
*1931-1935*

Area	Multiplier	Coefficient


Year	Unit	Coefficient	Land Value
19			



*Rear View*

Surveyed by.....  
 (over)

Assessment 19



*10x14 = 140*  
*12x30 = 360*  
*500 - 1/2*

Portland, Maine  
 Assessment 19  
 Name  
 Owner  
 Street  
 Block  
 Use of Bldg.  
 Tenants and Rooms  
 Rentals  
 Age  
 Condition of Repair

Class  
 Exterior  
 Plumbing  
 Finish  
 Halls  
 Foot-Roofing  
 Windows  
 Miscellaneous

Foundation  
 Heating  
 Light  
 Basement  
 Construction  
 Ceiling

Ground Area  
 Cubic Feet  
 Utility Dep.  
 Dep. Per cent.  
**Sound Value, \$**  
 Land  
 Front  
 COMPUTATION  
 Year  
 Unit  
 Coefficient  
 Land Value

Surveyed by.....  
 (over)



**Owner:** Lillian A. Smith  
**Address:** Rear N. Side Seashore Avenue, Peaks Island, Portland, Maine  
**Use:** Summer Dwelling  
**Local Code:** Block 85F Lot 18 Book 98 Page 1  
**MMN item number:** 86312  
**Notes:** Akso known as "Rockmere".