

Portland, Maine
 Assessment 1924
 Name Cushing Charles B
 Owner Cushing Charles B
 Street Long Island No. 1-4
 Block Pl. Bldg. Building Lot 1-4
 Use of Bldg. Hotel Name Long Island
 Tenants and Rooms 297 dining room, parlor, office
 Rentals 52
 Age 52
 Condition of Repair Fair
 Valuation 2170


Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	Finish
Store Building	Tapestry Brick	Plain
Office	Com. Brick	Hardwood
Factory	Galv. Iron	Halls
Storage	Stone	Wood
Stables	Terra Cotta	Plaster
Garage, private	Concrete	Marble
Garage, public		
Theatre		
Club House		
Cottage		
Foundation	Heating	Roof - Roofing
Brick	Stove in kitchen	Shingle
Stone	Furnace	Slate
Concrete	Hot Water	Gravel
Pile	Steam	Prepared
Basement	Light	Asbestos
Full	Oil	Flat
Cement Floor	Gas	Hip
Waterproof	Electric	Gable
Construction	Floor	Dormers
Frame	Common	Windows
Brick	Hardwood	Plain Glass
Tile	Re-Concrete	Wire Glass
Blocks	Concrete Slab	Shutters
Stucco	Waterproof	Miscellaneous
Re-Concrete		Elevator
Mill		Sprinkler
Steel Frame		Fire Escape
		Refrigerator
		Vacuum Cleaner
		Safes and Vaults
		Telephone Equip.

Ground Area 1968-38 Height.....
 Cubic Feet..... Unit.....
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land 2 1/2 A Corner..... Interior..... Alley.....
 Front..... Depth..... =..... ft.

COMPUTATION
 700
 2500 - 1931 = 2250


Area	Multiplier	Coefficient	
Year	Unit	Coefficient	Land Value
19			



2170

Surveyed by Johnson & Casey
 (Remarks on other Side)

Remarks about Buildings
 Dining room, front hall & helps dining room have hardwood floors



10x12 = 120
 8x26 = 208
 6x88 = 528
 24x82 = 1968 - 38

26
 18
 208
 26
 428

82
 24
 328
 164
 1968

Remarks about Land

Remarks about Personal Property



Owner: Charles E. Cushing
Address: N. Side Island Avenue and Cushing Street, Long Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 93I Lot 2 Book 92 Page 3
MMN item number: 86792