

1924 Portland Tax Records: Cushing property, Island Avenue, Long Island, Portland, 1924

Portland, Maine
 Assessment 1924
 Name *Cushing, Charles E.* 2-2
 Owner *Cushing, Charles E.*
 Street *Long Island* No. _____
 Block *93-J-1* Lot _____
 Use of Bldg. *Stable* Name _____
 Tenants and Rooms *Owner-2*
 Rentals *Owner*
 Age *18-20*
 Condition of Repair *Fair*
 _____ *V2091-A*


Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior <input checked="" type="checkbox"/> Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete No Heating Stove Furnace Hot Water Steam No Light Oil Gas Electric	No Plumbing Common Individual Open Set tubs No Finish Plain Hardwood Halls <i>Rough</i> Wood Terrazzo Marble No Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers	Foundation Brick Stone Concrete Pile	Basement <input checked="" type="checkbox"/> Full Cement Floor Waterproof No Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Floor <input checked="" type="checkbox"/> Common Hardwood Re-Concrete Concrete Slab Waterproof	Windows <input checked="" type="checkbox"/> Plain Glass Wire Glass Shutters	Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
---	--	---	---	--	--	---	--

Ground Area *600-28* Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____

Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.
 COMPUTATION

300-1931-#295

Area	Multiplier	Coefficient	
Year	Unit	Coefficient	Land Value
19			



Surveyed by *Vahneson Casey*

(over) *2/19*

Portland, Maine
 Assessment 1924
 Name *Cushing, Charles E.*
 Owner *Cushing, Charles E.*
 Street *Long Island* No. _____
 Block *93-J-1* Lot _____
 Use of Bldg. *Stable* Name _____
 Tenants and Rooms *Owner-2*
 Rentals *Owner*
 Age *18-20*
 Condition of Repair *Fair*
 _____ *V2091-A*

20x30 = 600-28

2091

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior <input checked="" type="checkbox"/> Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete No Heating Stove Furnace Hot Water Steam No Light Oil Gas Electric	No Plumbing Common Individual Open Set tubs No Finish Plain Hardwood Halls <i>Rough</i> Wood Terrazzo Marble No Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers	Foundation Brick Stone Concrete Pile	Basement <input checked="" type="checkbox"/> Full Cement Floor Waterproof No Construction Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	Floor <input checked="" type="checkbox"/> Common Hardwood Re-Concrete Concrete Slab Waterproof	Windows <input checked="" type="checkbox"/> Plain Glass Wire Glass Shutters	Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.
---	--	---	---	--	--	---	--

Ground Area *600-28* Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____

Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.
 COMPUTATION

Area	Multiplier	Coefficient	
Year	Unit	Coefficient	Land Value

Surveyed by *Vahneson Casey*

(over)

1924 Portland Tax Records: Cushing property, Island Avenue, Long Island, Portland, 1924



Owner: Charles E. Cushing
Address: Island Avenue, Long Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 93I Lot 1 Book 92 Page 3
MMN item number: 86794