

NON-RESIDENT

Portland, Maine
 Assessment 19 ¹⁰⁰ ~~500~~
 Name NON-RESIDENT
 Owner Zwicker Florence C. Williams
 Street Long Island Part lot 33 No. 33
 Block 95 ^{103-B-5} Lot _____
 Use of Bldg. S.D. Name _____
 Tenants and Rooms Owner - 5
 Rentals Owner
 Age 20-30
 Condition of Repair Fair
 Picture # 2426

Class	Exterior	Plumbing
Bungalow	<input checked="" type="checkbox"/> Clapboards	Common <u>1-5</u>
Single House	<input checked="" type="checkbox"/> Siding	Individual
Two family	<input checked="" type="checkbox"/> Shingles	Open
Three family	<input checked="" type="checkbox"/> Stucco	Set tubs
Apartment	Paper	Finish <u>Rough</u>
Store Building	Tapestry Brick	<input checked="" type="checkbox"/> Plain
Office "	Com. Brick	<input checked="" type="checkbox"/> Hardwood
Factory "	Galv. Iron	<input checked="" type="checkbox"/> Halls <u>Rough</u>
Storage "	Stone	Wood
Stables	Terra Cotta	Terrazzo
Garage, private	Concrete	Marble
Garage, public		
Theatre		
Club House	Heating	Roof - Roofing
<input checked="" type="checkbox"/> Cottage	<input checked="" type="checkbox"/> Stove	<input checked="" type="checkbox"/> Shingle
	<input checked="" type="checkbox"/> Furnace	Slate
	<input checked="" type="checkbox"/> Hot Water	Gravel
	<input checked="" type="checkbox"/> Steam	Prepared
Foundation		Asbestos
Brick	Light	Flat
Stone	<input checked="" type="checkbox"/> Oil	<input checked="" type="checkbox"/> Hip <u>Hansard</u>
<input checked="" type="checkbox"/> Concrete <u>Tests</u>	<input checked="" type="checkbox"/> Gas	Gable
Pile	Electric	Dormers
Basement <u>No</u>		
Full		
Cement Floor	Floor	Windows
Waterproof	<input checked="" type="checkbox"/> Common	<input checked="" type="checkbox"/> Plain Glass
	Hardwood	Wire Glass
Construction	Re-Concrete	Shutters
<input checked="" type="checkbox"/> Frame	Concrete Slab	Miscellaneous
Brick	Waterproof	Elevator
Tile		Sprinkler
Blocks	Ceiling	Fire Escape
Stucco	Plaster	Refrigerator
Re-Concrete	Metal	Vacuum Cleaner
Mill	Panelled	Safes and Vaults
Steel Frame	<input checked="" type="checkbox"/> Rough	Telephone Equip.

Ground Area Height.....
 Cubic Feet..... Unit.....cts.
 Utility Dep.
 Dep.Per cent.
Sound Value, \$


Land ⁹⁹⁵ ~~500~~ Corner Interior Alley
 Front Depth =ft.

COMPUTATION

100
550 - 1931 - 500

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			



Surveyed by Johnson & Casey
 (Remarks on other Side)



Owner: Florence C. Zwicker
Address: S. Side Island Avenue, East End, Long Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 103B Lot 5 Book 93 Page 1
MMN item number: 87181