

Portland, Maine
 Assessment 19 3-4

Name
 Owner *Woodbury Frank H Jr.*

Street *Long Island* No.
 Block *103-X-8* Lot

Use of Bldg. *Bar* Name
 Tenants and Rooms *Vacant-1*

Rentals *Vacant*
 Age *Old*

Condition of Repair *Very Poor*
 2134-B

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	
Store Building	Tapes try Brick	Finish
Office	Com. Brick	Plain
Factory	Galv. Iron	Hardwood
Storage	Stone	Balls <i>Rough</i>
Stables	Terra Cotta	Wood
Garage, private	Concrete	Terrazzo
Garage, public	<i>Brook</i>	Marble
Theatre	Heating	Floor-Roofing
Club House	Stove	Shingle
Cottage	Furnace	Slate
	Hot Water	Gravel
	Steam	Prepared
Foundation		Asbestos
Brick	Light	Flat
Stone	Oil	Hip
Concrete	Gas	Cable
Pile	Electric	Dormers
Basement <i>No</i>		
Full	Floor	Windows
Cement Floor	Common	Plain Glass
Waterproof	Hardwood	Wire Glass
	Re-Concrete	Shutters
Construction	Concrete Slab	
Frame	Waterproof	Miscellaneous
Brick		Elevator
Tile	Ceiling	Sprinkler
Blocks	Plaster	Fire Escape
Stucco	Metal	Refrigerator
Re-Concrete	Panelled	Vacuum Cleaner
Mill	<i>Rough</i>	Safes and Vaults
Steel Frame		Telephone Equip.


Ground Area Height
 Cubic Feet Unit ds.
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land Corner Interior Alley
 Front Depth = ft.

COMPUTATION

25 ✓

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			



Surveyed by *Johnson & Casey*
 3-4

(over)



Owner: Frank H. Woodbury Jr.
Address: S. side Island Avenue, Long Island, Portland, Maine
Use: Barn
Local Code: Block 103K Lot 8 Book 93 Page 3
MMN item number: 87211