

Portland, Maine
 Assessment 19
 Name *Doughty, Grace E.* 2-2
 Owner *Doughty, Grace E.*
 Street *Long Island* No.
 Block *10.3-6-29* Lot
 Use of Bldg. *Shed* Name
 Tenants and Rooms *1-1*
 Rentals *Relatives*
 Age *75*
 Condition of Repair *Very poor* 2286-A

Class
 Bungalow
 Single House
 Two family
 Three family
 Apartment
 Store Building
 Office
 Factory
 Storage
 Stables
 Garage, private
 Garage, public
 Theatre
 Club House
 Cottage
 Cottage
 Foundation
 Brick
 Stone
 Concrete
 Pile
 Sills
 Basement
 Full
 Cement Floor
 Waterproof
 Construction
 Frame
 Brick
 Tile
 Blocks
 Stucco
 Re-Concrete
 Mill
 Steel Frame

Exterior
 Clapboards *No*
 Siding
 Shingles
 Stucco
 Paper
 Tapestry Brick *No*
 Com. Brick
 Galv. Iron
 Stone
 Terra Cotta
 Concrete
 Heating
 Stove
 Furnace
 Hot Water
 Steam
 Light
 Oil
 Gas
 Electric
 Floor
 Common
 Hardwood
 Re-Concrete
 Concrete Slab
 Waterproof
 Ceiling
 Plaster
 Metal
 Panelled
 Rough

Plumbing
 Common
 Individual
 Open
 Set tubs
 Finish
 Plain
 Hardwood
 Halls *Rough*
 Wood
 Terrazzo
 Marble
 Roof-Roofing
 Shingle
 Slate
 Gravel
 Prepared
 Asbestos
 Flat
 Hip
 Gable
 Dormers
 Windows
 Plain Glass
 Wire Glass
 Shutters
 Miscellaneous
 Elevator
 Sprinkler
 Fire Escape
 Refrigerator
 Vacuum Cleaner
 Safes and Vaults
 Telephone Equip.


Ground Area Height
 Cubic Feet Unit cts.
 Utility Dep.
 Dep. Per cent.
Sound Value, \$

Land Corner Interior Alley
 Front Depth = ft.
 COMPUTATION

✓

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			



Surveyed by *P. Insons Casey*
 2-2
 (over)

1924 Portland Tax Records: Doughty property, H. Doughty Land, Long Island, Portland, 1924



Owner: Horace E. Doughty
Address: H. Doughty Land, Long Island, Portland, Maine
Use: Shed
Local Code: Block 103G Lot 29 Book 93 Page 2
MMN item number: 87380