

Portland, Maine
 Assessment 19 ²¹⁰⁰ ~~1300~~ ₁₃₀₀

Name
 Owner Keniston Susie A

Street Long Island N.E. side Leavitt St

Block 94 ¹⁰²⁻⁶⁻² Lot

Use of Bldg. Dwelling Name

Tenants and Rooms 1-7

Rentals answer

Age 8

Condition of Repair Fair

2020

Class	Exterior	Plumbing ^{no}
<input checked="" type="checkbox"/> Bungalow	<input checked="" type="checkbox"/> Clapboards	<input checked="" type="checkbox"/> Common
<input checked="" type="checkbox"/> Single House	<input type="checkbox"/> Siding	<input type="checkbox"/> Individual
<input type="checkbox"/> Two family	<input type="checkbox"/> Shingles	<input type="checkbox"/> Open
<input type="checkbox"/> Three family	<input type="checkbox"/> Stucco	<input type="checkbox"/> Set tubs
<input type="checkbox"/> Apartment	<input type="checkbox"/> Paper	Finish
<input type="checkbox"/> Store Building	<input type="checkbox"/> Tapestry Brick	<input checked="" type="checkbox"/> Plain
<input type="checkbox"/> Office "	<input type="checkbox"/> Com. Brick	<input type="checkbox"/> Hardwood
<input type="checkbox"/> Factory "	<input type="checkbox"/> Galv. Iron	<input type="checkbox"/> Marble
<input type="checkbox"/> Storage "	<input type="checkbox"/> Stone	Halls ^{Plaster}
<input type="checkbox"/> Stables	<input type="checkbox"/> Terra Cotta	<input type="checkbox"/> Wood
<input type="checkbox"/> Garage, private	<input type="checkbox"/> Concrete	<input type="checkbox"/> Terrazzo
<input type="checkbox"/> Garage, public		<input type="checkbox"/> Marble
<input type="checkbox"/> Theatre	Heating	Roof - Roofing
<input type="checkbox"/> Club House	<input checked="" type="checkbox"/> Stove	<input type="checkbox"/> Shingle
<input type="checkbox"/> Cottage	<input type="checkbox"/> Furnace	<input type="checkbox"/> Slate
	<input type="checkbox"/> Hot Water	<input type="checkbox"/> Gravel
	<input type="checkbox"/> Steam	<input type="checkbox"/> Prepared
Foundation		<input type="checkbox"/> Asbestos
<input checked="" type="checkbox"/> Brick	Light	<input type="checkbox"/> Flat
<input type="checkbox"/> Stone	<input checked="" type="checkbox"/> Oil	<input type="checkbox"/> Hip
<input type="checkbox"/> Concrete	<input type="checkbox"/> Gas	<input type="checkbox"/> Gable
<input type="checkbox"/> Pile	<input type="checkbox"/> Electric	<input type="checkbox"/> Dormers
Basement ^{no}		Windows
<input type="checkbox"/> Full	Floor	<input type="checkbox"/> Plain Glass
<input type="checkbox"/> Cement Floor	<input checked="" type="checkbox"/> Common	<input type="checkbox"/> Wire Glass
<input type="checkbox"/> Waterproof	<input type="checkbox"/> Hardwood	<input type="checkbox"/> Shutters
Construction	<input type="checkbox"/> Re-Concrete	Miscellaneous
<input checked="" type="checkbox"/> Frame	<input type="checkbox"/> Concrete Slab	<input type="checkbox"/> Elevator
<input type="checkbox"/> Brick	<input type="checkbox"/> Waterproof	<input type="checkbox"/> Sprinkler
<input type="checkbox"/> Tile	Ceiling	<input type="checkbox"/> Fire Escape
<input type="checkbox"/> Blocks	<input checked="" type="checkbox"/> Plaster	<input type="checkbox"/> Refrigerator
<input type="checkbox"/> Stucco	<input type="checkbox"/> Metal	<input type="checkbox"/> Vacuum Cleaner
<input type="checkbox"/> Re-Concrete	<input type="checkbox"/> Panelled	<input type="checkbox"/> Safes and Vaults
<input type="checkbox"/> Mill	<input type="checkbox"/> Rough	<input type="checkbox"/> Telephone Equip.
<input type="checkbox"/> Steel Frame		

Ground Area Height.....

Cubic Feet..... Unit.....cts.

Utility Dep.

Dep.Per cent.

Sound Value, \$

Land...8000... Corner..... Interior..... Alley


Front Depth =ft.

COMPUTATION

75
600 - 1931 - 1550

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			



2020

Surveyed by Johanson & Casey

(Remarks on other Side)



Owner: Susie A. Keniston
Address: North East Side Leavitt Street, Long Island, Portland, Maine
Use: Dwelling
Local Code: Block 100E Lot 2 Book 93 Page 1
MMN item number: 87448