


Portland, Maine  
 Assessment 19 2000  
 Name Leighton Flora E  
 Owner Peaks Island Lot 8  
 Street S. Side Island Ave  
 Block 84 A 44 D-10 Lot 23  
 Use of Bldg. RD. Name Rock Quarry  
 Tenants and Rooms 1-6  
 Rentals \_\_\_\_\_  
 Age 27  
 Condition of Repair Good


Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Stucco	Set tubs
Apartment	Paper	Finish
Store Building	Tapestry Brick	Plain
Office	Com. Brick	Hardwood
Factory	Galv. Iron	Halls
Storage	Stone	Wood
Stables	Terra Cotta	Terrazzo
Garage, private	Concrete	Marble
Garage, public	Heating	Roof - Roofing
Theatre	Stove	Shingle
Club House	Furnace	Slate
Cottage	Hot Water	Gravel
Foundation	Steam	Prepared
Brick	Light	Asbestos
Stone	Oil	Flat
Concrete	Gas	Rip
Pile	Electric	Gable
Basement	Windows	Dormers
1/2 Full	Floor	Plain Glass
Cement Floor	Common	Wire Glass
Waterproof	Hardwood	Shutters
Construction	Re-Concrete	Miscellaneous
Frame	Concrete Slab	Elevator
Brick	Waterproof	Sprinkler
Tile	Ceiling	Fire Escape
Blocks	Plaster	Refrigerator
Stucco	Metal	Vacuum Cleaner
Re-Concrete	Panelled	Safes and Vaults
Mill	Rough	Telephone Equip.
Steel Frame		

Ground Area 792-125 Height \_\_\_\_\_  
 Cubic Feet \_\_\_\_\_ Unit \_\_\_\_\_  
 Utility Dep. \_\_\_\_\_  
 Dep. \_\_\_\_\_ Per cent. \_\_\_\_\_  
 Sound Value, \$ \_\_\_\_\_  
 Land 7250 Corner \_\_\_\_\_ Interior \_\_\_\_\_ Alley \_\_\_\_\_  
 Front \_\_\_\_\_ Depth \_\_\_\_\_ = \_\_\_\_\_ ft.  
 COMPUTATION  
200  
2000 - 1924 - 1800



Surveyed by \_\_\_\_\_  
 (Remarks on other Side)

Remarks about Buildings



6x18 = 108  
 8x14 = 112  
 22x26 = 572  
 792 - 125

Remarks about Land

Remarks about Personal Property

Year 19

Surveyed by \_\_\_\_\_  
 (Remarks on other Side)



**Owner:** Flora E. Leighton  
**Address:** S. Side Island Avenue, Lot 8, Peaks Island, Portland, Maine  
**Use:** Dwelling  
**Local Code:** Block 84D Lot 10 Book 95 Page 1  
**MMN item number:** 87934