

1924 Portland Tax Records: Marriner property, N. Side Island Avenue, Long Island, Portland, 1924

Portland, Maine
 Assessment 19 24
 Name *Marriner Frank A*
 Owner *Marriner Frank A*
 Street *Long Island* No. *5-6*
 Block *97-A-19* Lot
 Use of Bldg. *Storage Shed* Name
 Tenants and Rooms *Vacant - 1*
 Rentals *Vacant*
 Age *Old*
 Condition of Repair *Very poor* *2100-D*

Class	Exterior	Plumbing
Bungalow	Clapboards	Common
Single House	Siding	Individual
Two family	Shingles	Open
Three family	Paper	Set tubs
Apartment		
Store Building	Tapestry Brick	Finish
Office	Com. Brick	Plain
Factory	Galv. Iron	Hardwood
Storage <i>Shed</i>	Stone	Wood
Stables	Terra Cotta	<i>Walls Rough</i>
Garage, private	Concrete	Terrazzo
Garage, public	Marble	Marble
Theatre	Heating	Foot-Roofing
Club House	Stove	Shingle
Cottage	Furnace	Slate
	Hot Water	Gravel
	Steam	Prepared
Foundation		Asbestos
Brick	Light	Flat
Stone	Oil	Hip
Concrete	Gas	<i>v Gable - Gal. Iron</i>
Pile	Electric	Dormers
<i>v Posts</i>		
Basement <i>No</i>	Floor	Windows
Full	Common	Plain Glass
Cement Floor	Hardwood	Wire Glass
Waterproof	Re-Concrete	Shutters
	Concrete Slab	
Construction	Waterproof	Miscellaneous
Frame		Elevator
Brick	Ceiling	Sprinkler
Tile	Plaster	Fire Escape
Blocks	Metal	Refrigerator
Stucco	Panelled	Vacuum Cleaner
Re-Concrete	Rough	Safes and Vaults
Mill		Telephone Equip.
Steel Frame		

Ground Area *280-1S* Height
 Cubic Feet Unit cts.
 Utility Dep.
 Dep. Per cent.
Sound Value, \$
 Land Corner Interior Alley
 Front Depth = ft.
 COMPUTATION
 0'

Area	Multiplier	Coefficient

Year	Unit	Coefficient	Land Value
19			



Surveyed by *P. Lawrence Casey*

(over)

Portland, Maine
 Assessment 19 24
 Name
 Owner
 Street No.
 Block Lot
 Use of Bldg. Name
 Tenants and Rooms
 Rentals
 Age
 Condition of Repair

10x28 = 280-1S

Exterior
 Clapboards
 Siding
 Shingles
 Paper
 Tapestry Brick
 Com. Brick
 Galv. Iron
 Stone
 Terra Cotta
 Concrete
 Marble

Plumbing
 Common
 Individual
 Open
 Set tubs

Finish
 Plain
 Hardwood
 Wood
 Terrazzo
 Marble

Foot-Roofing
 Shingle
 Slate
 Gravel
 Prepared
 Asbestos
 Flat
 Hip
 Gable
 Dormers

Windows
 Plain Glass
 Wire Glass
 Shutters

Miscellaneous
 Elevator
 Sprinkler
 Fire Escape
 Refrigerator
 Vacuum Cleaner
 Safes and Vaults
 Telephone Equip.

Foundation
 Brick
 Stone
 Concrete
 Pile

Basement
 Full
 Cement Floor
 Waterproof

Construction
 Frame
 Brick
 Tile
 Blocks
 Stucco
 Re-Concrete
 Mill
 Steel Frame

Ceiling
 Plaster
 Metal
 Panelled
 Rough

Ground Area
 Cubic Feet
 Utility Dep.
 Dep. Per cent.
Sound Value, \$
 Land Corner Interior Alley
 Front Depth = ft.
 COMPUTATION

1924 Portland Tax Records: Marriner property, N. Side Island Avenue, Long Island, Portland, 1924



Owner: Frank A. Marriner
Address: N. Side Island Avenue, Long Island, Portland, Maine
Use: Storage Shed
Local Code: Block 97A Lot 19 Book 92 Page 5
MMN item number: 88158