

1924 Portland Tax Records: Randall property, S. Side Island Avenue, Peaks Island, Portland, 1924


Portland, Maine
 Assessment 19
 Name *✓* Randall Mrs. L.B. 2-2
 Owner Randall Mrs. L.B.
 Street Island Ave. - Side No. _____
 Block Church Hvr. 87-Y-26 Lot
 Use of Bldg. S.C. Name _____
 Tenants and Rooms 1-2
 Rentals owner
 Age 2
 Condition of Repair Good 1636

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Heating Stove Furnace Hot Water Steam Light Oil Gas Electric Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Ceiling Plaster Metal Panelled Rough	Plumbing Common Individual Open Set tubs Finish Plain Hardwood Halls Wood Terrazzo Marble Froof-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Plain Glass Wire Glass Shutters Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Saves and Vaults Telephone Equip.
---	---	--

Ground Area 308-78 Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____

Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.
 COMPUTATION
250-1931-#225
1921 Sup

Area	Multiplier	Coefficient	
Year	Unit	Coefficient	Land Value
19			



1636

Surveyed by _____
 (over) *2-2*

Portland, Maine
 Assessment 19
 Name _____
 Owner _____
 Street _____ No. _____
 Block _____
 Use of Bldg. _____ Name _____
 Tenants and Rooms _____
 Rentals _____
 Age _____
 Condition of Repair _____

141
 (1)

14x22 = 308-18

Class Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	Exterior Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete Heating Stove Furnace Hot Water Steam Light Oil Gas Electric Floor Common Hardwood Re-Concrete Concrete Slab Waterproof Ceiling Plaster Metal Panelled Rough	Plumbing Common Individual Open Set tubs Finish Plain Hardwood Halls Wood Terrazzo Marble Froof-Roofing Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers Windows Plain Glass Wire Glass Shutters Miscellaneous Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Saves and Vaults Telephone Equip.
---	---	--

Ground Area _____ Height _____
 Cubic Feet _____ Unit _____ cts.
 Utility Dep. _____
 Dep. _____ Per cent. _____
Sound Value, \$ _____

Land _____ Corner _____ Interior _____ Alley _____
 Front _____ Depth _____ = _____ ft.
 COMPUTATION

Area	Multiplier	Coefficient	
Year	Unit	Coefficient	Land Value
19			

Surveyed by _____
 (over)

1924 Portland Tax Records: Randall property, S. Side Island Avenue, Peaks Island, Portland, 1924



Owner: Lizzie B. Randall
Address: S. Side Island Avenue, Peaks Island, Portland, Maine
Use: Summer Dwelling
Local Code: Block 87Y Lot 26 Book 95 Page 2
MMN item number: 88564
Notes: Permanent Residence, 15 Lloyd Street, Winchester, Mass.