


Portland, Maine  
 Assessment 19 <sup>1100</sup> <sub>8300</sub>  
 Name Stanforde William A  
 Owner Stanforde William A  
 Street W Side Arbutus Ave No. 88  
 Block 88-A 88-E-2 Lot 88  
 Use of Bldg. S.D. Name Arbutus  
 Tenants and Rooms 1-7  
 Rentals ?  
 Age 257  
 Condition of Repair Poor 1648

|   |   |  |
|---|---|--|
| <b>Class</b><br>Bungalow<br>Single House<br>Two family<br>Three family<br>Apartment<br>Store Building<br>Office<br>Factory<br>Storage<br>Stables<br>Garage, private<br>Garage, public<br>Theatre<br>Club House<br>Cottage | <b>Exterior</b><br>Clapboards<br>Siding<br>Shingles<br>Stucco<br>Paper<br>Tapes try Brick<br>Com. Brick<br>Galv. Iron<br>Stone<br>Terra Cotta<br>Concrete | <b>Plumbing</b><br>Common<br>Individual<br>Open<br>Set tubs  |
| <b>Foundation</b><br>Brick<br>Stone<br>Concrete<br>Pile   | <b>Heating</b><br>Stove<br>Furnace<br>Hot Water<br>Steam  | <b>Finish</b><br>Plain<br>Hardwood   |
| <b>Basement</b><br>Full<br>Cement Floor<br>Waterproof   | <b>Light</b><br>Oil<br>Gas<br>Electric  | <b>Halls</b><br>Wood<br>Terrazzo<br>Marble   |
| <b>Construction</b><br>Frame<br>Brick<br>Tile<br>Blocks<br>Stucco<br>Re-Concrete<br>Mill<br>Steel Frame   | <b>Floor</b><br>Common<br>Hardwood<br>Re-Concrete<br>Concrete Slab<br>Waterproof  | <b>Foot-Roofing</b><br>Shingle<br>Slate<br>Gravel<br>Prepared<br>Asbestos<br>Flat<br>Hip<br>Gable<br>Dormers                           |
|   | <b>Ceiling</b><br>Plaster<br>Metal<br>Panelled<br>Rough   | <b>Windows</b><br>Plain Glass<br>Wire Glass<br>Shutters  |
|   |   | <b>Miscellaneous</b><br>Elevator<br>Sprinkler<br>Fire Escape<br>Refrigerator<br>Vacuum Cleaner<br>Safes and Vaults<br>Telephone Equip. |

Ground Area ..... Height .....  
 Cubic Feet ..... Unit ..... cs.  
 Utility Dep. ....  
 Dep. .... Per cent. ....  
**Sound Value, \$** .....  
 Land <sup>2520</sup> 4900 Corner Interior Alley  
 Front ..... Depth ..... = ..... ft.  
 COMPUTATION  
 50  
 657 500 **\$400** - 1931-350  
 1930

| Area | Multiplier | Coefficient |
|------|------------|-------------|
|      |            |             |

| Year | Unit | Coefficient | Land Value |
|------|------|-------------|------------|
| 19   |      |             |            |



Surveyed by.....  
 (over)

Portland, Maine  
 Assessment 19 .....  
 Name .....  
 Owner .....  
 Street ..... No. ....  
 Block ..... Lot .....  
 Use of Bldg. .... Name .....  
 Tenants and Rooms .....  
 Rentals .....  
 Age .....  
 Condition of Repair .....  
 1648

not shown

|   |   |  |
|---|---|--|
| <b>Class</b><br>Bungalow<br>Single House<br>Two family<br>Three family<br>Apartment<br>Store Building<br>Office<br>Factory<br>Storage<br>Stables<br>Garage, private<br>Garage, public<br>Theatre<br>Club House<br>Cottage | <b>Exterior</b><br>Clapboards<br>Siding<br>Shingles<br>Stucco<br>Paper<br>Tapes try Brick<br>Com. Brick<br>Galv. Iron<br>Stone<br>Terra Cotta<br>Concrete | <b>Plumbing</b><br>Common<br>Individual<br>Open<br>Set tubs  |
| <b>Foundation</b><br>Brick<br>Stone<br>Concrete<br>Pile   | <b>Heating</b><br>Stove<br>Furnace<br>Hot Water<br>Steam  | <b>Finish</b><br>Plain<br>Hardwood   |
| <b>Basement</b><br>Full<br>Cement Floor<br>Waterproof   | <b>Light</b><br>Oil<br>Gas<br>Electric  | <b>Halls</b><br>Wood<br>Terrazzo<br>Marble   |
| <b>Construction</b><br>Frame<br>Brick<br>Tile<br>Blocks<br>Stucco<br>Re-Concrete<br>Mill<br>Steel Frame   | <b>Floor</b><br>Common<br>Hardwood<br>Re-Concrete<br>Concrete Slab<br>Waterproof  | <b>Foot-Roofing</b><br>Shingle<br>Slate<br>Gravel<br>Prepared<br>Asbestos<br>Flat<br>Hip<br>Gable<br>Dormers                           |
|   | <b>Ceiling</b><br>Plaster<br>Metal<br>Panelled<br>Rough   | <b>Windows</b><br>Plain Glass<br>Wire Glass<br>Shutters  |
|   |   | <b>Miscellaneous</b><br>Elevator<br>Sprinkler<br>Fire Escape<br>Refrigerator<br>Vacuum Cleaner<br>Safes and Vaults<br>Telephone Equip. |

Ground Area ..... Height .....  
 Cubic Feet ..... Unit ..... cs.  
 Utility Dep. ....  
 Dep. .... Per cent. ....  
**Sound Value, \$** .....  
 Land ..... Corner Interior Alley  
 Front ..... Depth ..... = ..... ft.  
 COMPUTATION  
 50  
 657 500 **\$400** - 1931-350  
 1930

| Area | Multiplier | Coefficient |
|------|------------|-------------|
|      |            |             |

| Year | Unit | Coefficient | Land Value |
|------|------|-------------|------------|
| 19   |      |             |            |

Surveyed by.....  
 (over)

[www.mainememory.net/item/89291](http://www.mainememory.net/item/89291)  
Collections of City of Portland - Planning & Development



**Owner:** Wiliam A. Stanforde  
**Address:** W. Side Arbutus Avenue, Peaks Island, Portland, Maine  
**Use:** Summer Dwelling  
**Local Code:** Block 88E Lot 2 Book 94 Page 1  
**MMN item number:** 89291