

Portland, Maine  
**Assessment 19** *Boogind Annie R*  
 Name *Rackleff HPA*  
 Owner *Central Ave.*  
 Street *Central Ave.* No. *15*  
 Block *87-F* *87-F-3* Lot *15*  
 Use of Bldg. *Storage* Name  
 Tenants and Rooms *1-1*  
 Rentals *owner*  
 Age  
 Condition of Repair *Fair*  
*395-B*

<b>Class</b> Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	<b>Exterior</b> Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete	<b>Plumbing</b> <i>no</i> Common Individual Open Set tubs
<b>Foundation</b> Brick Stone Concrete Pile	<b>Heating</b> <i>no</i> Stove Furnace Hot Water Steam	<b>Finish</b> <i>no</i> Plain Com. Brick Hardwood
<b>Basement</b> <i>no</i> Full Cement Floor Waterproof	<b>Light</b> <i>no</i> Oil Gas Electric	<b>Halls</b> <i>Rough</i> Wood Terrazzo Marble
<b>Construction</b> Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	<b>Floor</b> Common Hardwood Re-Concrete Concrete Slab Waterproof	<b>Foot-Roofing</b> Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers
	<b>Ceiling</b> Plaster Metal Panelled Rough	<b>Miscellaneous</b> Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.

Ground Area..... Height.....  
 Cubic Feet..... Unit.....cts.  
 Utility Dep.....  
 Dep..... Per cent.  
**Sound Value, \$**  
 Land..... Corner..... Interior..... Alley.....  
 Front..... Depth..... =.....ft.  
**COMPUTATION**

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value
19			

Portland, Maine  
**Assessment 19**  
 Name  
 Owner  
 Street  
 Block  
 Use of Bldg.  
 Tenants and Rooms  
 Rentals  
 Age  
 Condition of Repair

*Not Shown*

<b>Class</b> Bungalow Single House Two family Three family Apartment Store Building Office Factory Storage Stables Garage, private Garage, public Theatre Club House Cottage	<b>Exterior</b> Clapboards Siding Shingles Stucco Paper Tapestry Brick Com. Brick Galv. Iron Stone Terra Cotta Concrete	<b>Plumbing</b> Common Individual Open Set tubs
<b>Foundation</b> Brick Stone Concrete Pile	<b>Heating</b> Stove Furnace Hot Water Steam	<b>Finish</b> Plain Com. Brick Hardwood
<b>Basement</b> Full Cement Floor Waterproof	<b>Light</b> Oil Gas Electric	<b>Halls</b> Wood Terrazzo Marble
<b>Construction</b> Frame Brick Tile Blocks Stucco Re-Concrete Mill Steel Frame	<b>Floor</b> Common Hardwood Re-Concrete Concrete Slab Waterproof	<b>Foot-Roofing</b> Shingle Slate Gravel Prepared Asbestos Flat Hip Gable Dormers
	<b>Ceiling</b> Plaster Metal Panelled Rough	<b>Miscellaneous</b> Elevator Sprinkler Fire Escape Refrigerator Vacuum Cleaner Safes and Vaults Telephone Equip.

Ground Area..... Height.....  
 Cubic Feet..... Unit.....cts.  
 Utility Dep.....  
 Dep..... Per cent.  
**Sound Value, \$**  
 Land..... Corner..... Interior..... Alley.....  
 Front..... Depth..... =.....ft.  
**COMPUTATION**

Area		Multiplier	Coefficient
Year	Unit	Coefficient	Land Value

1924 Portland Tax Records: Assessor's Record, Rackleff property, Central Avenue, Peaks Island, Portland

**Owner:** H. A. Rackleff  
**Address:** Central Avenue, Peaks Island, Portland, Maine  
**Use:** Storage  
**Local Code:** Block 87F Lot 3 Book 94 Page 4  
**MMN item number:** 89851  
**Notes:** Annie R. Googins also listed as owner